United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

Number SA104780 Avitas Engineering This certificate, issued to Miami, FL 33126 certifies that the change in the type design for the following product with the lim Federal Aviation therefor as specified hereon meets the airworthiness requirements of Part Regulations. STC Surrender processed: Original Product - Trype Certificate Number: A23WE Approval by: 74 Lockheed Model: LA1011 Date: 23 /EB 2009 Description of Type Design Change: Installation of the Litton LTN-211 Omega Navigation System in accordance with Eastern Air Lines Engineering Report No. E-1002, Revision B, Appendix A, dated October 25, 1978 (or later approved revision). Added Notes at Surrender: Future unsafe conditions existing in the product can result in an airworthiness directive requiring correction of the unsafe condition before further flight. If there is no entity to comply with 14 CFR 21.99(a), Required design changes, the existence of an unsafe condition might result in permanently grounding of the aircraft. 2. Replacement parts might not be available in the future. This Supplemental Type Certificate requires Airplane Flight Manual Supplement dated February 7, 1979, and is limited to Lockheed L-1011 series airplanes. This approval should not be extended to other airplanes of this series on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will produce no adverse affect upon the airworthiness of that airplane. This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration. Date reissued: June 5, 1992 June 14, 1978 Date of application: Date amended: February 7, 1979 Date of issuance: Bry direction of the Administrator Manager, Atlanta Aircraft

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Certification Office